

FIG. 1




FIG. 2 (Prior Art)




FIG. 3 (Prior Art)





FIG. 4

On_hook Insertion Loss



____ IL_No_resistor ____ IL_500 Ohms ___ LL_1000 Ohms __ *__ IL_2500 Ohms __ *__ IL_10000 Ohms

FIG. 5

Off_hook Insertion Loss




FIG. 6